





带销六星盘头机螺钉



- 星形中间带销的螺栓，普通的六星扳手无法放入。
- 能很好地传递扭矩且不会打滑、使用性优越。



	M3	M4	M5	M6
dk	5.5	7	9	10.5
k	2	2.6	3.3	3.9
驱动尺寸	T10	T20	T25	T30



- 材料・铁
- 表面处理 三价镀锌

规格		零件号 #z	每箱数量
d	L		
M3	5	TX110305ZP3	3,000
	6	TX110306ZP3	2,500
	8	TX110308ZP3	2,000
	10	TX110310ZP3	2,000
	12	TX110312ZP3	2,500
	15	TX110315ZP3	2,000
	16	TX110316ZP3	2,000
	18	TX110318ZP3	1,500
M4	20	TX110320ZP3	1,500
	6	TX110406ZP3	2,000
	8	TX110408ZP3	2,000
	10	TX110410ZP3	1,500
	12	TX110412ZP3	1,500
	15	TX110415ZP3	1,000
	16	TX110416ZP3	1,000
	20	TX110420ZP3	900
M5	25	TX110425ZP3	700
	30	TX110430ZP3	500
	8	TX110508ZP3	1000
	10	TX110510ZP3	900
	12	TX110512ZP3	800
	15	TX110515ZP3	700
	16	TX110516ZP3	700
	20	TX110520ZP3	500
M6	25	TX110525ZP3	700
	8	TX110608ZP3	600
	10	TX110610ZP3	600
	12	TX110612ZP3	500
	15	TX110615ZP3	500
	16	TX110616ZP3	400
	18	TX110618ZP3	400
	20	TX110620ZP3	300
	25	TX110625ZP3	500
	30	TX110630ZP3	400

- 材料 铁
- 表面处理 黑色三价镀锌

规格		零件号 #	每箱数量
d	L		
M3	5	TX110305ZB3	3,000
	6	TX110306ZB3	2,500
	8	TX110308ZB3	2,000
	10	TX110310ZB3	2,000
	12	TX110312ZB3	2,500
	15	TX110315ZB3	2,000
	16	TX110316ZB3	2,000
	18	TX110318ZB3	1,500
M4	20	TX110320ZB3	1,500
	6	TX110406ZB3	2,000
	8	TX110408ZB3	2,000
	10	TX110410ZB3	1,500
	12	TX110412ZB3	1,500
	15	TX110415ZB3	1,000
	16	TX110416ZB3	1,000
	20	TX110420ZB3	900
M5	25	TX110425ZB3	700
	30	TX110430ZB3	500
	8	TX110508ZB3	1000
	10	TX110510ZB3	900
	12	TX110512ZB3	800
	15	TX110515ZB3	700
	16	TX110516ZB3	700
	20	TX110520ZB3	500
M6	25	TX110525ZB3	700
	8	TX110608ZB3	600
	10	TX110610ZB3	600
	12	TX110612ZB3	500
	15	TX110615ZB3	500
	16	TX110616ZB3	400
	18	TX110618ZB3	400
	20	TX110620ZB3	300
	25	TX110625ZB3	500
	30	TX110630ZB3	400

Please see page 40-41 for tools.

专用工具请看 40 — 41 页

